

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s): Keaney, *et al.*

Assignee: Cisco Technology, Inc.

Patent No: 7,062,703

Issue Date: June, 13, 2006

Application No.: 10/629,383

Filed: July 28, 2003

Title: EARLY DETECTION OF FALSE START-
OF-PACKET TRIGGERS IN A WIRELESS
NETWORK NODE

REQUEST FOR CERTIFICATE OF CORRECTIONS

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Dear Commissioner:

The above patent contains significant error(s) as indicated on the attached Certificate of Correction form (submitted in duplicate).

 X Such error(s) arose through the fault of the Patent and Trademark Office. It is requested that the certificate be issued at no cost to the applicant.

However, if it is determined that the error(s) arose through the fault of applicant(s), please note that such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the certificate of Correction is respectfully requested. The Commissioner is authorized to charge Deposit Account No. 50-0292 any required fee. A duplicate of this request is attached.

 Such error(s) arose through the fault of applicant(s). A credit card charge form for the fee is enclosed. Each such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the certificate of Correction is respectfully requested.

Such error(s) specifically:

In column 10, line 17, kindly change “**RX_11A_CHRKSER**” to -- **RX_11A_CHKSER**--.

In column 10, line 27, kindly change “**RX_11A_CHRKSER**” to -- **RX_11A_CHKSER**--.

The undersigned requests being contacted at (510) 547-3378 if there are any questions or clarifications, or if there are any problems with issuance of the Certificate of Correction.

Respectfully Submitted,

July 10, 2006 _____
Date

/Dov Rosenfeld/ #38687 _____
Dov Rosenfeld, Reg. No. 38687
Agent of Record.

Address for correspondence:

Dov Rosenfeld
5507 College Avenue, Suite 2,
Oakland, CA 94618
Tel.(510) 547-3378; Fax: (510) 291-2985

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s): Keaney, *et al.*

Assignee: Cisco Technology, Inc.

Patent No: 7,062,703

Issue Date: June, 13, 2006

Application No.: 10/629,383

Filed: July 28, 2003

Title: EARLY DETECTION OF FALSE START-
OF-PACKET TRIGGERS IN A WIRELESS
NETWORK NODE

REQUEST FOR CERTIFICATE OF CORRECTIONS

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Dear Commissioner:

The above patent contains significant error(s) as indicated on the attached Certificate of Correction form (submitted in duplicate).

 X Such error(s) arose through the fault of the Patent and Trademark Office. It is requested that the certificate be issued at no cost to the applicant.

However, if it is determined that the error(s) arose through the fault of applicant(s), please note that such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the certificate of Correction is respectfully requested. The Commissioner is authorized to charge Deposit Account No. 50-0292 any required fee. A duplicate of this request is attached.

 Such error(s) arose through the fault of applicant(s). A credit card charge form for the fee is enclosed. Each such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the certificate of Correction is respectfully requested.

Such error(s) specifically:

In column 10, line 17, kindly change “**RX_11A_CHRKSER**” to -- **RX_11A_CHKSER**--.

In column 10, line 27, kindly change “**RX_11A_CHRKSER**” to -- **RX_11A_CHKSER**--.

The undersigned requests being contacted at (510) 547-3378 if there are any questions or clarifications, or if there are any problems with issuance of the Certificate of Correction.

Respectfully Submitted,

July 10, 2006 _____
Date

/Dov Rosenfeld/ #38687 _____
Dov Rosenfeld, Reg. No. 38687
Agent of Record.

Address for correspondence:

Dov Rosenfeld
5507 College Avenue, Suite 2,
Oakland, CA 94618
Tel.(510) 547-3378; Fax: (510) 291-2985

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,062,703

DATED : June 13, 2006

INVENTOR(S) : Keaney, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

In column 10, line 17, kindly change “RX_11A_CHRKSER” to -- RX_11A_CHKSER--.

In column 10, line 27, kindly change “RX_11A_CHRKSER” to -- RX_11A_CHKSER--.

MAILING ADDRESS OF SENDER (Atty/Agent of Record):
Dov Rosenfeld, Reg. No. 38687
5507 College Avenue, Suite 2
Oakland, CA 94618

PATENT NO: 7,062,703
No. of additional copies

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,062,703

DATED : June 13, 2006

INVENTOR(S) : Keaney, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

In column 10, line 17, kindly change “RX_11A_CHRKSER” to -- RX_11A_CHKSER--.

In column 10, line 27, kindly change “RX_11A_CHRKSER” to -- RX_11A_CHKSER--.

MAILING ADDRESS OF SENDER (Atty/Agent of Record):
Dov Rosenfeld, Reg. No. 38687
5507 College Avenue, Suite 2
Oakland, CA 94618

PATENT NO: 7,062,703
No. of additional copies